WS PROSOY GUIDE

PREPARED BY WIC SUPPLIES



MELT ING TEMPERATURE	Temperature to melt the wax to in melter.	**80-85°** Celsius
ADD FRAGRANCE	Temperature to add fragrance oil.	**75°** Celsius
POUR TEMPERATURE	Temperature to pour wax into vessels after mixing.	**70°** Celsius
OPTIMAL ROOM TEMPERATURE	Ideal room temperature for best wax finish.	**21-24°** Celsius

By Makers - For Makers
WIC SUPPLIES
ESTABLISHED 2023

This wax usage guide was prepeared by the testing team at Wic Supplies and is to serve only as general guidance not instruction. Our wax must be tested before production and results can vary significantly based on fragrance oil, jar, environmental conditions and other factors.